TYPE DESIGNATION

P B R - ____

• Type of Button

1: Flush

2: Salient

5: Flush Head with Cylinder Lock

7: Half Shrouded

52: Cylinder Lock 2-Position

62: Knob 2-Position

· Contact Arrangement

10: 1NO 11: 1NO1NC

20: 2NO 12: 1NO2NC

30: 3NO 13: 1NO3NC

40: 4NO 21: 2NO1NC

01: 1NC 22: 2NO2NC

02: 2NC 31: 3NO1NC


03: 3NC

04: 4NC


MODEL LIST

Appearance	Operator	Color of Button	Туре	Remarks
	Flush head	Red Green Black	PBR-1-[]	General Purpose
	Salient head	Red*4 Green Black	PBR-2-[]	General Purpose
	Half shrouded head	Red*4 Green Black	PBR-7-	Protection against accidental contact
	Knob 2-position	〈Knob〉 Black	PBR-62-[]]	1NC Unit 1NO Unit
	Cylinder lock 2-position	(Cylinder) Chrome plated	PBR-52-[]]	1NC Unit 1NO Unit


Type PBLR-



Type PBR-5-



DRILLING PLAN FOR MOUNTING HOLE



Note: The 5mm hole is used to stop whirl. If nameplates are not used or nameplate does not have any whirl-stop, the hole is not required.

Diameter of Mounting Part: 30mm


• MOUNTING PITCH

2-CONTACTS 103.5 4-CONTACTS 133.5


 To avoid interference when mounting units in close proximity to one another, refer to the dimensions specified below for proper separation. Units mounted closer together than specified may affect operations and result in unsatisfactory performance.

M3.5 TERMINAL SCREW

M3.5 TERMINAL SCREW



 Refer to the dimensions specified below for proper mounting and separation from other magnetic materials. Units mounted closer together than specified may affect operations and result in unsatisfactory performance.



PRECAUTIONS FOR MOUNTING

ACAUTION

- Switch mounting screw torque must be 3.09N · m (31.5kgf · cm) ±10%.
- (Do not tighten screws too firmly to prevent them from damaging.)

 Operate push-buttons in control part at 2.16N (0.22kgf) or less.
- Operate push-buttons in control part at 2.16N (0.22kgf) or less. (Do not push them too strong to prevent them from damaging.)

○ RESTRICTION

- This switch cannot be used where dust and cutting powder are present.
 - (They might come into gear in the switch and lock it.)

PRECAUTIONS FOR WIRING

! CAUTION

- ●Connecting wires must be 2mm² or less.
- ◆Terminal screw torque must be 0.65N · m (6.5kgf · cm) ±10%. (Do not tighten screws too firmly to prevent them from damaging.)